Hazards	ls the hazard	What is the risk?	Risk rating H = High		Is this	Action/to do list/outstanding controls	Person responsible	Signature and date	
	present? Y/N		M = Medium L = Low	(When all controls are in place risk will be reduced).	in place?	*Risk rating applies to outstanding controls outlined in this column		completed	
Contact with moving parts		Injury of persons using the machine which is defective or incorrectly installed General injuries Cuts/ lacerations Amputations Entanglement	н	Drive mechanism appropriately guarded. Guard removable only with the use of a tool or alternatively be fitted with an interlocking guard mechanism					
			defective or	н	Headstock mandrel protected as required]			
			н	The stop control has priority over the start control					
			Н	In the event of power supply interruption, automatic restart is prevented after restoration of the power supply					
			н	Appropriate turning tools used, which are maintained sharp and in good condition					
			н	The stop control is more prominent than the start control to facilitate ease and speed of access when it is necessary to turn off the machine					
			Н	Machine is fitted with an emergency stop control (usually red domed mushroom type head on yellow housing) in an appropriate location, which is easily accessible in an emergency	-				
			Н	The flap type emergency stop control (flap-stop is a normal start and stop contact, which is equipped with a yellow flap and red mushroom-type push buttons, covering both the start and stop contacts) is not acceptable where there is a need for an emergency stop					
			н	In the event of power supply interruption, automatic restart is prevented after restoration of the power supply					
Contact by persons other than the operator with moving machine		Entanglement, pinching, amputation of body parts	H	Safe operational areas should be marked out clearly around machines					
Ejected material, flying debris and or ejected work pieces		Injury, eye injury	н	Work piece is securely fixed in place and any chuck wrench removed					
		н	Appropriate eye protection is worn						

Technologies - No.65 Wood Lathe (List additional hazards, risks and controls particular to your school using the blank template no.69)

Technologies - No.65 Wood Lathe cont'd. (List additional hazards, risks and controls particular to your school using the blank template no.69)

Hazards	Is the hazard present? Y/N	What is the risk?	Risk rating H = High M = Medium L = Low	Controls (When all controls are in place risk will be reduced).	control	Action/to do list/outstanding controls *Risk rating applies to outstanding controls outlined in this column	Person responsible	Signature and date completed
Electric shock, electrocution, burns, death		Electric shock/ fire/burns	Н	Visual check carried out prior to use				
			Н	Machines are serviced by a competent person and service records kept as part of the maintenance schedule	-			
			Н	Defective electrical equipment shall be clearly identified, labelled as out of use. Ensure all faults are recorded in log book. Ensure any previous faults have recieved attention. Report defects to person in control of workplace to ensure all items are repaired or replaced	+			
			Н	The operation of the RCD is checked by pressing the test button regularly and the RCD is tested periodically by a competent person to ensure that it operates at correct leakage current (leakage current not exceeding 30 mA in a time of not more than 0.3 seconds). Applicable to plug & sockets arrangements				
			Н	Ensure cables are free from damage, do not have any non-standard joints or show any signs of overheating	_			
			Н	Ensure equipment is disconnected or isolated when not in use	-			
Unsupervised use of machines		Unsupervised use leading to injury	Н	Pupils are prohibited from using certain machinery				
			Н	Pupils are supervised by teacher when using any machine				
			Н	Pupils are instructed by teacher before using any machine				
			H	Machinery to be used by teachers only should be clearly identified				

Hazards	ls the hazard present? Y/N	What is the risk?	Risk rating H = High M = Medium L = Low	Controls (When all controls are in place risk will be reduced).	Is this control in place?	Action/to do list/outstanding controls *Risk rating applies to outstanding controls outlined in this column	Person responsible	Signature and date completed
Unsecured machine		Movement of machine leading to injury during use	H	Machine securely fixed to the floor or bench and work piece appropriately secured				
Inadequate signage		Inadequate information and warnings leading to unsafe use of machine and injury	М	Warning signs are prominently located and maintained in good condition				
Ingestion of contaminated material		Poisoning or ill health	м	Food and drink are prohibited in working area				
Contact with hazardous materials		Exposure to hazardous materials	м	Personal hygiene is promoted (washing of hands, use of barrier creams etc.)				

Technologies - No.65 Wood Lathe cont'd. (List additional hazards, risks and controls particular to your school using the blank template no.69)

If there is one or more **High Risk (H)** actions needed, then the risk of injury could be high and immediate action should be taken. **Medium Risk (M)** actions should be dealt with as soon as possible. **Low Risk (L)** actions should be dealt with as soon as practicable.