

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
2019	No Domestic or Workplace Electrocutions in Ireland in 2019					
2018	No Domestic or Workplace Electrocutions in Ireland in 2018					
07/10/2017 (died on the 19th Oct)	Restaurant	Male	Adult Over 50 (56)	Work	Cleaning in Restaurant. Accessible part became live.	230 V
1st March 2016	Outdoor Farm	Male	Adult 25- 50 (32)	Work	Tree-Felling- Wet rope touched OH Line	20 kV
June-2015	Outdoor Garden	Male	Adult Over 50 (59)	Non-Work (Gardening)	Ladder touching OH Line	20kV
22 nd Sep2014	Indoor Electrical Sub-Station	Male	Adult Over 50 (54)	Work	Switchgear	38 kV
25 th August 2014	House	Male	Adult Over 50	Non-Work	Heater	LV
18-Jul-2013	Farm Outhouse	Male	14	Workplace	Power Hose & Cable Reel	LV
16-Jan-2013	Electrical Sub- Station	Male	Adult < 25	Work	38 kV Bus-Bar	38 kV
2012	House	Male		Non-Work	Electric-Heater	LV
24-Sep-2012	Countryside	Male	Adult Over 50 (58)	Work	Overhead Line	LV
13th March 2012	Construction Site	Male	Adult 25- 50	Work	Overhead Line	20 kV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
10-Dec-11	Household	Male	Adult 25-50		Electric Shower	LV
24-Sep-11	Workshop	Male	Adult Over 50	Work	Cable Lead-Compressor	LV
15-Jul-2010	Mobile home park	Male	Adult 25-50	Non-Work	Mobile home became live	LV
29-May-10	Domestic Garage	Male		Non-Work	Possibly self inflicted	LV
19-May-10	Hedgerow	Male	Adult 25-50	Work	Pole saw made contact with overhead line	20kV
01-Feb-10	Indoor 10kV substation	Male	Adult 25-50	Non-Work	Energised Cable and hack saw.	10kV
09-Oct-09	Landscaped Garden	Male	Adult 25-50	Work	Flexible Cable	LV
25-Jul-08	Construction Site/Farm	Male	Adult 25-50	Work	Truck Mounted Crane	10 kV
09-Sep-07	Private housing/Apartment development	Male	Under 12	Non Work	Vandalised Lamp-post	LV
23-Apr-07	Construction	Male	Adult < 25	Work	Floating Concrete	10 kV
Dec-05	Construction	Male	Adult 25-50	Work	Concrete Conveyor	10kV Line
Oct-05	Construction	Male	Adult 25-50	Work	Metal Stay	20 kV
Oct-05	Construction	Male	Adult < 25	Work	Installing Concrete Slab	10kV
2005	Industrial	Male	Adult 25-50	Work	Welder in Hospital	LV
2005	Household	Male	Adult 25-50	Non Work	Washing Machine	LV
Nov-04	Farm	Male	Adult 25-50	Non Work	Lighting Tower	20kV Line

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
Nov-04	Farm	Male	Adult 25-50	Non Work	Lighting Tower	20 kV
Nov-04	Construction	Male	Adult 25-50	Work	Guttering	10 kV
Jun-04	Farm	Male	Adult < 25	Work	Silage Harvester	10kV Line
13-Jan-04	Yard	Male	Adult 25-50	Work	Truck Mounted Crane	20kV Line
2003	Industrial	Male	Adult 25-50	Work	Exploding Circuit Breaker	10 kV
2003	Industrial	Male	Adult 25-50	Work	Exploding Circuit Breaker	10 kV
2003	Construction	Male	Adult < 25	Work	Concrete Chute	10 kV
2002	Industrial	Male	Adult 25-50	Work	Crane moving Welder	10 kV
2002	Countryside	Male	Adult 25-50	Work	Cutting Timber	20 kV
2002	Garden	Male	Adult 25-50	Non Work	Secateurs cut cable	LV
2002	Utility Substation	Male	Under 12	Non Work	Child Climbed into Sub	10 kV
Nov-01	Construction	Male	Adult 25-50	Work	Tipping Tarmacadam	10 kV
Oct-01	Farm	Male	Adult < 25	Work	Live Parts in a Poultry shed	LV
Oct-01	Construction	Male	Adult 25-50	Work	Truck Mounted Crane	38 kV
Jun-01	Industrial	Male	Adult 25-50	Work	Plumbing in Kitchen	LV
Dec-00	Construction	Male	Adult < 25	Work	Lighting POD	LV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
Dec-00	Construction	Male	Adult 25-50	Work	Lighting POD	LV
Dec-00	Farmland	Female	Adult Over 50	Non Work	Fallen ESB Line	10 kV
Nov-00	ESB Network	Male	Adult 25-50	Work	ESB Technician Working	10 kV
Sep-00	Household	Male	Adult < 25	Non Work	Changing Bulb	LV
Aug-00	Household	Male	Under 12	Non Work	Toddler-Nail in Socket	LV
Jun-00	Milking Parlour	Male	Adult 25-50	Work	Milking Machine Became Live	LV
Sep-00	Industrial	Male	Adult 25-50	Work	Electrician Killed by Metalwork	LV
Jan-00	Basement of Apartment block	Male	Adult < 25	Work	Delivery Person Copper Pipes on Broken Light Switch	LV
14-Dec-99	Utility substation	Male	Adult < 25	Non Work	Man Gained Access to Substation	110kV
07-Sep-99	Construction	Male	Adult 25-50	Work	Concrete Conveyor	10 kV
03-Aug-99	Industrial	Male	Adult 25-50	Work	Elec. Craftsman working on 3 phase panel	LV
19-Nov-98	Industrial	Male	Adult 25-50	Work	Elec. Craftsman working on 3 phase Motor	LV
20-Oct-98	Railway	Male	Adult 25-50	Non Work	Man on Dart Powerline	1500 VDC
01-Oct-98	Household	Male	Adult 25-50	Non Work	Working in Radio Hut	LV
04-Jun-98	Household	Male	Teenager	Non work	Having a shower	LV
01-May-98	Farm	Male	Teenager	Work	Mains on Electric Fence	LV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
21-Aug-97	Farm	Male	Adult < 25	Work	Power Washer in Piggery	LV
04-Jul-97	Farm	Male	Adult < 25	Work	Welding in a Shed	LV
01-Mar-97	Construction	Male	Adult < 25	Work	Roofer Hit Line	10 kV
18-Nov-96	Halting site	Male	Adult Over 50	Work	Truck Mounted Crane	10 kV
16-Oct-96	Construction	Male	Adult 25-50	Work	Tipper Truck Driver stepping off truck	10kV
06-Jun-96	Construction	Male	Adult 25-50	Work	Concrete Conveyor	10 kV
23-Mar-96	Industrial	Male	Teenager	Work	Teenager in Contact with Wire slung on 10 kV line	10kV
23-Jan-96	Household	Female	Adult < 25	Non Work	Woman Having Shower	LV
1995	Household	Male	Adult Over 50	Non Work	Contact with Bare Conductors in Socket	LV
15-Aug-95	Sports field	Male	Adult 25-50	Work	Portable Scaffold on Sports Pitch	10 kV
12-Apr-95	Countryside	Male	Adult < 25	Work	Truck Tipping	10 kV