

An tÚdarás Sláinte agus Sábháilteachta Health and Safety Authority Solata 289 389 Solata comah@hsa.ie swww.hsa.ie

Public Information on a lower-tier establishment as required by Regulation 25

Information on lower-tier establishments

All establishments subject to the *COMAH Regulations 2015* have submitted a notification in a standard form to the Authority. This includes information on their location, the hazard categories of the dangerous substances present with an indication of their dangers, emergency action information and sources of additional relevant information.

General Duties on Operators

Operators have a general duty to identify all the major accident hazards in their establishment, take all necessary measures to prevent major accidents and to limit the consequences of such accidents to human health and the environment.

Public information for a lower-tier establishment

This establishment is subject to the COMAH Regulations 2015 and has submitted a notification to the Authority.

The following information, which has been extracted from the notification, fulfils the requirements of Regulation 25(3)(a).

The date of the most recent COMAH inspection (added by the Central Competent Authority) can also be found in the table below.



Notification History

Unilin Insulation Ireland Limited

Version	Reason Date	
1.0	First notification 19/05/2017	
2.0	Information update 21/12/2020	
3.0	Information update 06/01/2022	
4.0	Company name change 02/03/2023	
5.0	Information update 15/12/2023	



An tÚdarás Sláinte agus Sábháilteachta Health and Safety Authority Solata 289 389 Solata <u>www.hsa.ie</u> www.hsa.ie

Regulation 25 information for Unilin Insulation Ireland Limited

Trade Name Trade Name Trade Name Trade Name Establishment Address Address Liscarton Industrial Estate, Kells Road, Navan County Co. Meath Eircode Dotification Details Tier Lower Tier Activity General engineering, manufacturing and assembly Dangerous Substance Hazard Categories / Named Substances P5a Flammable Liquids Dangerous Characteristics /Hazard H224 H224 H224 H225 Hatand Statements H224 H226 UPG Hatard Categories / Characteristics /Hazard Members of the public likely to be affected will be warned by the Gardal or Fire Service Behaviour to take in event of major accident Currently no offsite risk Statements Inspection Most recent COMAH Inspection (updated quarterly): More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: Cres unit, Heatth & Safety Authority, Metropolitan Building, James Joyce Street, Dublin J. Information Where further relevant information available Further information about the isestablishment may be obtained upon request, subject to the requirements of Regulation 26, from: Cres unit, H	Operator Name	Registered Name	Unilin Insulation Ireland Limited
Establishment Address Address Liscarton Industrial Estate, Kells Road, Navan County Co. Meath Eircode C15NP79 Notification Details Tier Lower Tier Activity General engineering, manufacturing and assembly Dangerous Substance information Hazard Categories, / Named Substances P5a Flammable Liquids E 2 Hazardous to the Aquatic Environment, P2 Flammable Gases LPG Dangerous Characteristics /Hazard Statements H225 H411 H220 Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Ehaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection (updated quarterly): B* September 2023 Where more detailed information on inspection available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCFS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority			
County Co. Meath Eircode C15NP79 Notification Details Tier Lower Tier Activity General engineering, manufacturing and assembly Dangerous Substance information Hazard Categories / Named Substances P5a Flammable Liquids E2 Hazardous to the Aquatic Environment, P2 Flammable Gases LPG Dangerous Characteristics /Hazard Statements H224 H225 H411 H220 Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Behaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection (updated quarterly): B th September 2023 Where more detailed information on inspection available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 (Access to information and confidentiality) information may also be available from the Health and Safety Authority, on request, under the Access to	Establishment Address		Liscarton Industrial Estate Kells Road Navan
Eircode C15NP79 Notification Details Tier Lower Tier Activity General engineering, manufacturing and assembly Dangerous Substance information Hazard Categories / Named Substances P5a Flammable Liquids E2 Hazardous to the Aquatic Environment, P2 Flammable Gases LPG Dangerous Characteristics /Hazard Statements H224 H225 H411 H220 Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Behaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 (Access to information and confidentiality)' information may also be available from the Health and Safety Authority, on request, under the Access to			
Notification Details Tier Lower Tier Activity General engineering, manufacturing and assembly Dangerous Substance information Hazard Categories. / Named Substances P5a Flammable Liquids E2 Hazardous to the Aquatic Environment, P2 Flammable Gases LPG Dangerous Characteristics /Hazard Statements Hazard Hazard Emergency Information How the public Will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Behaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection (updated quarterly): More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to			
Activity General engineering, manufacturing and assembly Dangerous Substance information Hazard Categories Named Substances PSa Flammable Liquids E2 Hazardous to the Aquatic Environment, P2 Flammable Gases LPG Dangerous Characteristics /Hazard Statements H324 H325 H411 H220 Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Behaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection (updated quarterly): More detailed information on inspection available Information Where further relevant information available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to	Notification Dotails		
Dangerous Substance information Hazard Categories / Named Substances P5a Flammable Liquids E2 Hazardous to the Aquatic Environment, P2 Flammable Gases LPG Dangerous Characteristics /Hazard Statements H224 H225 H411 H220 Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Inspection Most recent COMAH Inspection (updated quarterly): Currently no offsite risk Where more detailed information on inspection available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 (Access to information and confidentiality)) information may also be available for may also be available for the Health and Safety Authority, on request, under the Access to	Notification Details	-	
Information Named Substances E2 Hazardous to the Aquatic Environment, P2 Flammable Gases LPG Dangerous Characteristics /Hazard Statements H224 H225 H411 H220 Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Inspection Most recent COMAH Inspection (updated quarterly): Currently no offsite risk Where more detailed information on inspection available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 (Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		Activity	General engineering, manufacturing and assembly
Information Name 3005tances P2 Flammable Gases LPG Dangerous H224 Characteristics /Hazard H225 H411 H220 Emergency Information How the public will be warned Warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Behaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection (updated quarterly): Where more detailed information about the inspection and the related information about the inspection and the related information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to	Dangerous Substance	Hazard Categories /	
LPG Dangerous Characteristics /Hazard Statements H224 H225 H411 H220 Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Behaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection (updated quarterly): 8 th September 2023 Where more detailed information on inspection available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to	information	Named Substances	
Dangerous Characteristics /Hazard Statements H224 H225 H411 H220 Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Behaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection (updated quarterly): 8 th September 2023 Where more detailed information on inspection available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to			
Characteristics / Hazard StatementsH225 H411 H220Emergency Information emergency InformationHow the public will be warnedMembers of the public likely to be affected will be warned by the Gardai or Fire ServiceEmergency Information Behaviour to take in event of major accidentMembers of the public likely to be affected will be warned by the Gardai or Fire ServiceInspectionMost recent COMAH Inspection (updated quarterly):More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Meteropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		Dangerous	
Statements H411 H220 Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Behaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection (updated quarterly): 8 th September 2023 Where more detailed information on inspection available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		-	
Emergency Information How the public will be warned Members of the public likely to be affected will be warned by the Gardai or Fire Service Behaviour to take in event of major accident Currently no offsite risk Inspection Most recent COMAH Inspection (updated quarterly): 8th September 2023 Where more detailed information on inspection available More detailed information plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentialty') information may also be available from the Health and Safety Authority, on request, under the Access to			
warnedby the Gardai or Fire ServiceBehaviour to take in event of major accidentCurrently no offsite riskInspectionMost recent COMAH Inspection (updated quarterly):8th September 2023Where more detailed information on inspection availableMore detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to			HZZU
warnedby the Gardai or Fire ServiceBehaviour to take in event of major accidentCurrently no offsite riskInspectionMost recent COMAH Inspection (updated quarterly):8th September 2023Where more detailed information on inspection availableMore detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to	Emergency Information	How the public will be	Members of the public likely to be affected will be warned
event of major accidentCurrently no offsite riskInspectionMost recent COMAH Inspection (updated quarterly):8th September 2023Where more detailed information on inspection availableMore detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to			
Inspection Most recent COMAH 8th September 2023 Inspection (updated quarterly): Where more detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		Behaviour to take in	
Inspection (updated quarterly): More detailed information about the inspection and the related information on inspection available More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1. Information Where further relevant information available Further information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		event of major accident	Currently no offsite risk
quarterly):More detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to	Inspection	Most recent COMAH	8 th September 2023
Where more detailed information on inspection availableMore detailed information about the inspection and the related inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		Inspection (updated	
information on inspection availablerelated inspection plan can be obtained upon request, subject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		quarterly):	
Information off inspection availablesubject to the requirements of Regulation 26, from: CCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		Where more detailed	
Inspection availableCCPS unit, Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		information on	
Health & Safety Authority, Metropolitan Building, James Joyce Street, Dublin 1.InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to		inspection available	
James Joyce Street, Dublin 1. Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to			,
Information Where further relevant information available Further information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to			
InformationWhere further relevant information availableFurther information about this establishment may be obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to			
information available obtained, in the first instance, from the operator. Subject to Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to	Information	Where further relevant	
Regulation 26 ('Access to information and confidentiality') information may also be available from the Health and Safety Authority, on request, under the Access to	mormation		,
Safety Authority, on request, under the Access to			Regulation 26 ('Access to information and confidentiality')
			mornation on the Environment Regulations.